

**DOE/SC Status Review of the
Muon to Electron Conversion Experiment (Mu2e) at Fermilab
February 23-25, 2021**

AGENDA
(All times are Central Time)

Tuesday, February 23, 2021

9:30 am	Executive Session (Closed).....	K. Fisher
10:30 am	Welcome	J. Lykken
10:40 am	Project Overview	R. Ray
11:40 am	WBS 4 Solenoids	M. Lamm
12:20 pm	Lunch	
1:00 pm	WBS 6 Tracker	R. Tschirhart
1:30 pm	Analysis of Schedule Delays and Cost Overruns	R. Ray
2:05 pm	Break	
2:20 pm	Subcommittee Breakout Sessions	
	• Session 1 Accelerator/Muon Beamline	
	• Session 2 Detectors	
	• Session 3 Joint Solenoid/Management (Restricted)	
4:15 pm	Full Committee Executive Session (Closed)	K. Fisher

Wednesday, February 24, 2021

10:00 am	Response to Questions	All
10:30 am	Subcommittee Breakout Sessions	
	• Session 1 Accelerator (if needed)	
	• Session 2 Detectors	
	• Session 3 Solenoids	
	• Session 4 Management	
12:30 pm	Lunch	
1:30 pm	Subcommittee Exec Sessions (Closed)	Review Team
3:30 pm	Executive Session (Closed)	K. Fisher

Thursday, February 25, 2021

10:00 am	Subcommittee Working Session/Dry Run
12:00 pm	Closeout Presentation
1:00 pm	Adjourn

BREAKOUT SESSION AGENDAS (All times are Central Time)

Tuesday, February 23, 2021

1. Accelerator

2:20 pm	Accelerator	S. Werkema
2:50 pm	Muon Beamline.....	G. Ginther
3:20 pm	Discussion.....	All

2. Detectors

2:20 pm	Vertical Slice Test & COVID Impacts	R. Bonventre
2:55 pm	Electronics (incl. LV & HV Systs) & COVID Impacts.....	V. Rusu
3:35 pm	Plane & Station Prod., Infrastructure & COVID Impacts	M. Yucel

3. Joint Management/Solenoids Breakout Session (Restricted)

2:20 pm	GA Technical Progress	T. Page
2:45 pm	GA Management issues	R. Ray
3:30 pm	TS Progress	V. Lombardo
4:00 pm	Discussion.....	All

Wednesday, February 24, 2021

1. Accelerator

10:30 am	Discussion (if needed)	All
----------	------------------------------	-----

2. Detectors

10:30 am	Panel Production & COVID Impacts	K. Heller
11:10 am	Discussion of Working Schedule.....	R. Tschirhart
11:30 am	Calorimeter	S. Miscetti
11:50 am	CRV	C. Dukes
12:10 pm	TDAQ	R. Rivera

3. Solenoids

10:30 am	Transportation Solenoid Assembly.....	P. Schlabach
10:50 am	Cryo Distribution	T. Tope
11:10 am	Installation & Commissioning	J. Brandt
11:30 am	Power Supplies	S. Hays
11:50 am	Field Mapping	S. Feher
12:10 pm	Quench Protection & Monitoring	D. Orris

4. Management Breakout Session

10:30 am	ES&H and COVID	R. Lewis
11:00 am	Integration	K. Byrum
11:30 am	Transition to Operations	G. Rakness
12:00 pm	Discussion.....	All